

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2141911-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

Issued to: ZENITEL NORWAY AS
24C SANDAKERVEIEN OSLO
Norway 0403

**This is to certify that
representative samples of**

AZOT7 - Audio/Video, Information and Communication
Technology Equipment Certified for Canada

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 NO. 62368-1-14, 2nd Ed., Issue Date: 2014-12-01

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2141911-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
Vingtor-Stentofon or Zenitel , TCIA-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-3(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-4(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-5(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-6(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-C1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-2 (a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-2+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-2141911-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

Vingtor-Stentofon or Zenitel , TCIV-3(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-3+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-5(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-5+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-6(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-6+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TKIA-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TKIS-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIS-1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIS-4, All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIV-1+, All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2149955-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

Issued to: ZENITEL NORWAY AS
24C SANDAKERVEIEN OSLO
Norway 0403

**This is to certify that
representative samples of**

AZOT - Audio/Video, Information and Communication
Technology Equipment

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 62368-1, 2nd Ed., Issue Date: 2014-12-01

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2149955-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
Vingtor-Stentofon or Zenitel , TCIA-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-3(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-4(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-5(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-6(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIS-C1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-2 (a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-2+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-2149955-0
Report Reference E317047-A6002-UL
Date 29-Oct-2021

Vingtor-Stentofon or Zenitel , TCIV-3(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-3+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-5(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-5+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-6(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TCIV-6+(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TKIA-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TKIS-2(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIS-1(a), (a) All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIS-4, All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom
Vingtor-Stentofon or Zenitel , TMIV-1+, All models may be followed by a letter or letter combination which specifies alternate software version and/or software configuration.	Intercom



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

